




MOULD BOLSTERS PS SERIES



Description and applications

- * 7 models available
- * Support by spheres to position moulds and/or systems on machine
- * Mechanical lift by cup springs.



Model	Number of spheres	Max force in kN	Dimensions						
			A	B	C	D	H	L	X
PS.13.05	5	1.5	30	12	15	18	29	120	2
PS.13.08	8	2.4						175	
PS.16.08	8	2.4	25	10	16	16	28	175	2
PS.18.05	5	1.5	30	12	18	18	32	120	2
PS.18.08	8	2.4						175	
PS.18.13	13	3.9						280	
PS.22.09	9	2.7	35	16	22	22	40	195	2